Abstract

In a method for safe data transfer between an intrinsically safe sensor and a non-intrinsically safe computer unit, data transfer occurs via an interface embodied as an Ex-barrier, or via a portable storage medium.